

LIGHT SPORT AIRCRAFT:  
**2007 Czech Aircraft Works Sportcruiser**



**CORBI AIR INC.**

11800 Salem Warren Rd. • Salem Air Park (38D) • Salem, OH 44460

corbiair@aol.com

Toll Free: 1-800-267-2424 or 330-337-1180

Equipment Specifications	
Year	2007
Manufacturer	CZECH AIRCRAFT WORKS
Model	SPORTCRUISER
Price	\$107,000 USD
Location	Edgewater, Florida
Condition	USED
Total Time	223 Hours
General Information	
Low time 2007 SportCruiser with no damage history	
Detailed Description	
<p><b>Airframe:</b> 223 hours since new</p>	
<p><b>Engine Specs:</b> 223 hours since new, Rotax 100 hp</p>	
<p><b>Prop(s):</b> 10 hours on a new, optional 2 blade Sensenich prop, ground adjustable, composite construction</p>	
<p><b>Modifications/Conversions:</b> Optional 2 blade Sensenich, ground adjustable, composite prop.</p>	
<p><b>Avionics/Radios:</b> Garmin GPS-396 w/Airgizmo Mount King KY-97 Transceiver Garmin GTX320 Transponder PM3000 Stereo Intercom ELT w/AK-450 Antenna TruTrak DigiFlight IIVS Autopilot</p>	
<p><b>Additional Equipment:</b> PANEL: Optional "6 Pack" Panel, Airspeed Indicator, Altimeter, Directional Gyro, Vertical Speed Indicator, Turn &amp; Bank, Attitude Indicator, Tachometer, Oil Temperature Gage, Cylinder Head Temp. Gage, Oil Pressure Gage, Fuel Pressure Gage, Left &amp; Right Fuel Gages, Volt Meter, Hobbs Meter</p> <p>FEATURES: Full Dual Controls, Locking Canopy, Carburetor Heat System, Dual Toe Brakes, Electric Elevator Trim, Liquid Cooled Cylinder Heads, Electric Aileron Trim, Two 15 gallon Wing Fuel Tanks, Cabin Heat, Tinted One Piece Canopy, Carpeted Cockpit Floor, Oil Cooler, Dual 4 Point Safety Harness, Upholstered Seats &amp; Backs, Fabric Covered Aft Storage, Fabric Covered Side Panels, Two Wing Lockers, Large NACA Air Vents, Engine Driven Fuel Pump, Dual Electronic CDI Ignition, Electric Wing Flaps, Aux Fuel Pump, Internal Corrosion Protection,, Two Map Pockets</p>	
<p><b>Exterior:</b> Upper White, Lower Taupe with Maroon Trim.</p>	
<p><b>Interior:</b> Two Tone Tan Cloth Seats with Tan Carpet, Side Panels, and rear baggage area.</p>	
<p><b>Inspection Status:</b> Annual Inspection due June 2011</p>	